

# Water Tank Projects

## Inspection

<b>Tank</b>	<b>Rehab Date</b>	<b>Rehab Type</b>	<b>Estimated Cost</b>
Gorrell Street	Fall 2004	Interior/Exterior Cleaning & Painting	\$1,000,000.00
Muir's Chapel High 4	Spring 2005	Exterior Cleaning & Painting	\$300,000.00

## New Construction

<b>Tank</b>	<b>Construction Date</b>	<b>Tank Type</b>	<b>Estimated Cost</b>
Knox Road	Summer/Spring 2003	1.0 mg Composite Tank	\$1.4 Million
Aycock Street	Fall 2003	1.0 mg Composite Tank	\$1.2 Million

1. More specific dates for the rehabilitation work will be noted as the specifications and contracts for the work are completed.
2. Cleaning of the tank involves using sand or steel shot to "blast" clean the old paint and debris from the existing surface. Any unused mounting brackets will be removed and the area repaired. Any irregularities in the tank surface such as weld burrs, weld splatter, or erection scars will be ground off to provide a smooth surface for the application of the coating.
3. The date for the exterior cleaning of Muir's Chapel High is an estimate.